



2019, vol. 23, no. 1, pp. 122–134 doi: 10.2478/rtuect-2019-0009 https://content.sciendo.com

In-Situ Moisture Assessment in External Walls of Historic Building using Non-Destructive Methods

Ritvars FREIMANIS¹*, Rasa VAISKUNAITE², Tereza BEZRUCKO³, Andra BLUMBERGA⁴

^{1,3,4} Institute of Energy Systems and Environment, Riga Technical University, Azenes iela 12/1, Riga, LV-1048, Latvia

²Department of Environmental Protection and Water Engineering, Vilnius Gediminas Technical University, Sauletekio al. 11, Vilnius, LT-10223, Lithuania

Abstract – In-situ measurements of a case study building located in Riga old town near the river Daugava has been carried out in this work. Performed measurements are moisture level of historic masonry, and interstitial monitoring of temperature and relative humidity between the layers of internal insulation and external wall. Obtained results are compared with outdoor weather data. Results show that during the cold months of the year no rising damp problem. No interstitial condensation under the internal insulation, and no risk of mold growth occur. However, the façade of the building tends to be highly influenced by the outdoor weather, and the moisture of the masonry increases during the rain load events.

Keywords – Dielectric measurement; internal insulation; interstitial relative humidity; masonry deterioration; microwave measurement; wind-driven rain

1. INTRODUCTION

High greenhouse gas emissions rate is driving climate change. One of the main causes is high energy demand from existing building stock [1], [2]. In Europe, historic buildings still account for as many as 24 to 35 % of the entire building stock. Moreover, the building stock of historic buildings composes from 27 to 42 %, of the final energy demand in Europe – depending on the country [3]. It is estimated that about 36 % of CO₂ emissions in the European Union (EU) comes from the building sector [4], [5].

The main reasons for the high energy consumption in the buildings depends on the physical elements, thermal properties and climate conditions [6]. The main reason for high energy consumption in historic buildings is poor thermal properties of the building envelope, in terms of high thermal transmittance or U-Value. In theory U-value can be calculated if the thermal conductivity of the material and boundary conditions are known, but in reality, this value can be influenced by moisture, cracks, etc. [7]. Nevertheless, moisture-caused problems are present in many historic buildings, that leads to degradation of building materials, unsuitable indoor air conditions and poor thermal properties of exterior walls [8]. Unhealthy indoor air quality can affect general senses of the human, reducing their work abilities and leading to health risks [9]. Jimenez-Besecos et al. in their research, concluded, that healthy indoor air quality (IAQ) can be achieved when retrofit of a historic building is done. Healthy IAQ in the study is defined as 19 to 20 °C temperature, 40 to 70 % relative humidity and CO₂ concentration below 1000 ppm [10].

As most of the thermal energy losses are through the opaque building envelope (exterior walls), insulation of exterior walls, can reduce energy consumption of the building and thereby reduce

^{*} Corresponding author.

E-mail address: ritvars.freimanis_1@rtu.lv

^{©2019} Ritvars Freimanis, Rasa Vaiskunaite, Tereza Bezrucko, Andra Blumberga.

This is an open access article licensed under the Creative Commons Attribution License (http://creativecommons.org/ licenses/by/4.0), in the manner agreed with Sciendo.

greenhouse gas emissions [11]. External walls can be insulated either from the outside or from the inside. To avoid exacerbation of moisture-related problems in the building, it is recommended to insulate the building from the outside. But almost in all cases insulation of historic buildings from the outside is not possible due to preservation of heritage value of the historic façade, or other limitations, such as space restrictions. Therefore internal insulation of exterior walls becomes the single best solution to reduce energy consumption of the historic building and thereby reduce greenhouse gas emissions [11]. At the same time, the renovation should not compromise the structural integrity and indoor air quality of the renovated building.

If the masonry moisture content exceeds 3 % of mass moisture content, there is a need to undertake action in order to reduce this moisture content before the renovation [12]. Moreover, if moisture sources in the masonry are not eliminated, further renovation is not recommended, considering masonry decay and other moisture-caused problems will reappear in a short period of time [8]. However, the situation that only one moisture source is present in the historic building is very rare, and many factors affecting the moisture content in the masonry makes it hard to clearly distinguish among the main moisture sources in the historic building. Therefore, to find a non-harmful renovation method a hygrothermal performance and moisture content of a historic masonry must be assessed. And to avoid oversized, inadequately expensive and ineffective interventions, preliminary monitoring of a building is recommended [13]. There are six main groups of moisture sources in the buildings: Raising dump, Wind-driven rain, Built-in moisture, Hygroscopic phenomena, Surface condensation, Damages in water systems, i.e. piping and gutter [14].

With new non-destructive moisture assessment technologies emerging and improving for moisture content assessment in-situ, the measurements are becoming more applicable to historic buildings, cause destructive methods such as drilling holes and inserting probes are mostly not preferable in historic facades. Test results obtained in-situ through the systematic surveys can be very helpful for the moisture source determination [8].

The main goal of this research is to study the application of internal insulation in historic buildings by assessing the possible moisture sources in the external wall and their impact on moisture content and moisture transport in the wall.

2. MATERIALS AND METHODS

2.1. Case Study Building

The case study building at Biskapa gate 6 in Riga, Latvia was selected for the in-situ measurements. This particular building was selected, because of complaints from building residents about the discomfort, in the form of increased indoor humidity levels. Another reason for choosing this building was the visible deterioration of the façade (Fig. 1).



Fig. 1. Case study at Biskapa gate 6: a) location of building and weather station in map; b) façade of the building [15].

The building is a three-story residential building with additional attic floor and one underground floor (basement). Building was built in 1880 and is located in the historic center of Riga, approximately 150 m from the river Daugava (Fig. 1). The building area is 120.9 m² with a 1511 m³ of construction volume. The building has two adjacent buildings, one on the North-West (NE) and another on the North-East (NE) side of the building. Both adjacent buildings are 1 story higher than the case study building. The South-West (SW) side of the building is the main façade, with the entrance from the street (Biskapa gate). The SE facing façade is the largest open area to the outdoor weather, such as wind driven rain, sun radiation and wind. The free space between the SE façade and next building. About 10 years ago the ground floor flat owner has installed internal insulation of glasswool (0.05 m) on the SE wall.

2.2. Methodology

Qualitative and quantitative methods have been used for determination of the possible moisture sources in the external wall masonry.

Qualitative analysis includes direct observation of the building to identify existing signs of decay and moisture caused damages.

Quantitative method includes moisture distribution evaluation of the building exterior wall in relative scales. Moisture of the wall was measured from the outside. Wall moisture measurements from the inside were limited due to applied internal insulation. The moisture assessment was carried out in two depths -2 cm and 20 cm deep in the masonry (including plaster). For these measurements a multifunction measuring device *Trotec* T3000 was used [16]. *Trotec* T3000 was used with two types of measurement probes for different measurement depths:

- Dielectric probe TS 660 SDI for 2 cm depth;
- Microwave probe TS 610 SDI for 20 cm depth.

Dielectric and microwave probe are both used for moisture distribution measurements in relative scale and cannot be directly compared with each other. Meaning that the same readings from both probes does not indicates same moisture contents.

For monitoring purposes, the measured South-East facing wall was divided into smaller squares forming a grid, approximately 0.4 m to 0.4 m each (Fig. 4). The same grid was used for the repeated moisture measurements over a period of time. Wall moisture measurements were started

in the autumn (September 21st of 2018) and were continued until the spring (March 5th of 2019). During the monitoring period, wall moisture was measured 5 times.

From the interior side of the wall, the monitoring system was installed, floor plan showing the measurement points are presented in Fig. 2.



Fig. 2. Cross section of monitored wall with measurement points.

The monitoring system started to collect data on 20th November 2018. Monitoring system included relative humidity and temperature monitoring in between the layers of the insulation of the external wall. Monitoring of the relative humidity and temperature in between the layers of the insulation was done using the *Honeywell HIH* 4000-002 and type T PFA insulated twin twisted pair thermocouple cable. Data logger *Campbell CR*1000 was used for data logging of these sensors. For the insertion of the monitoring system, a small hole with a diameter of 27 mm was drilled in the internally insulated wall. In total, two relative humidity and two temperature sensors were installed in the insulation layers. The sensor pairs were installed 20 cm below the hole, one pair between the wall and insulation and the other pair between the insulation and gypsum board. Additionally, temperature and relative humidity was measured near the interior surface of the insulated wall. After the insertion of the relative humidity and temperature sensors, the hole was refilled with mineral wool and gypsum board. To avoid extra moisture addition to the insulation system through the cut and to retain access to the sensors, no plaster was used to cover the hole.

Instead the gypsum board was sealed in place with masking tape, and additionally covered with vapor tight aluminium adhesive tape.

Weather data from the closest weather station were used. The weather station is located at the University of Latvia (Fig. 1) and the data are managed by the "*Latvian Environment, Geology and Meteorology Centre*" (LEGMC) [17].

3. **RESULTS AND DISCUSSIONS**

Visual inspection of the façade revealed severe material loss, i.e. plaster and reduced masonry thickness at the ground level. Moreover, multiple cracks and poor-quality craftsmanship was noticeable. Algae growth was also evident on some parts of the façade. However, no sign of efflorescence was noticed. There was also an observation of some repair jobs carried out, where some of the lost material (plaster, bricks) had been replaced with cement. Near the ground level on the west-facing wall, a loss of building material was observed. Material loss was most severe on the edges of the wall and under the window but was almost undetectable on the front facing wall (Fig. 3).



Fig. 3. Façade of the building: a) South-West façade; b) South corner; c) right corner of South-East façade; d) South-East façade.

Fig. 4 shows the moisture measurements for both the 2 cm and 20 cm depths. The obtained values indicate moisture in relative scale, from drier to more wet area, where 0 signifies the most-dry and 250 the most-wet value.

	- Top - Middle - Bottom																		
	134	147	149	128	125	159	181	155	147	82	128	153	168			142	116	82	143
	131	146	149	148	120	186	170	164	155	110	124	124	118			130	96	92	140
250	183	77	161	183	134	185	126	143	128	144	124	137	138			80	97	130	129
225	184	130	151	173	137	172	161	129	176	175	187	111	94			92	127	139	166
200	168	168	164	150	150	159	130	131	158	159	140	147	146	118	75	95	98	99	105
175	152	132	105	141	153	116	134	131	139	175	160	155	158	111	108	126	147	133	104
150	2 cm depth																		
125	52	45	45	52	39	43	45	67	63	38	44	34	47			37	52	41	43
100	57	47	47	44	33	55	79	59	67	33	52	35	53			54	57	54	57
75	64	48	48	54	45	44	80	61	74	65	47	53	63			54	46	32	43
50	60	57	57	62	39	42	47	54	75	38	61	30	65			64	56	46	69
25	63	72	72	76	61	41	53	57	58	65	44	55	52	35	47	68	44	37	49
0	50	43	43	55	64	52	40	41	56	72	50	60	58	50	47	70	55	40	36
	20 cm depth																		

Fig. 4. Moisture distribution in the wall, March 5th, year 2019.

The average moisture values for 20 cm depth of the external wall of all the measurement dates are presented in Table 1. The measurement difference between highest and lowest measured value varies from 45 in November to 65 in February.

	21st September	22 nd November	19th January	12th February	5 th March
Average	48.35	48.56	49.24	50.45	52.30
Max value	79	78	83	89	80
Min value	28	33	30	24	30
Mode	39	50	44	49	47
Median	48	47	48	49	52
Standard deviation	10.85	9.46	9.18	11.28	11.41

TABLE 1. AVERAGE VALUES OF 20 CM DEPTH MEASUREMENTS

TABLE 2. AVERAGE VALUES OF 2 CM DEPTH MEASUREMENTS

	21st September	22 nd November	19th January	12th February	5 th March
Average	99.84	123.95	107.12	119.58	137.59
Max value	182	190	161	161	187
Min value	49	13	14	16	75
Mode	126	126	100	125	147
Median	99	126	108.5	126	139
Standard deviation	28.87	30.98	26.44	21.21	26.99

For better understanding of moisture distribution in the wall and how it corresponds to the changing weather, the measurement area was divided in three sections (Fig. 7). The sections are

bottom section from ground up to 0.8 m, middle section from 0.8 m to 1.6 m and top section from 1.6 m to 2 m.

In Fig. 5 changes of average values in top, middle and bottom sections, for 20 cm depth measurements are presented. There has been an upward trend at the bottom section of the wall, during the measurement period. Likewise, the top section follows the upward trend, with the slight decrease from 1st to 2nd measurement. The moisture measurements of the middle section had a drop of average moisture value in January, but afterwards they start to follow an upward trend.



Fig. 5. Average moisture value changes for 20 cm depth measurements.

In Fig. 6 changes of average values in top, middle and bottom sections, for 2 cm depth measurements are illustrated. The 2 cm depth measurements follow a very similar trend as the 20 cm depth measurements in the middle section, with an increase in the period from the September to November, followed by a drop and then continuing an upward trend.



Fig. 6. Average moisture value changes for 2 cm depth measurements.

In Fig. 7 the average moisture measurement values are compared to each other and to average relative humidity period of 24-hours, prior to the measurements. It can be seen that 2 cm depth measurements, that represent moisture values near the surface, are more than two times greater

than 20 cm depth measurements that represent moisture values 20 cm inside the masonry. During the measurement period, average 20 cm depth measurements change only by 3.5 during the whole period, but maintain the upward trend. 2 cm depth measurements on the other hand fluctuate and change by a total of 37.75 during the measurement period.



Fig. 7. Average values of the wall moisture measurements and outdoor relative humidity

In Fig. 8 the correlation between the outdoor relative humidity and wall moisture is presented. The correlation observed is good for 2 cm depth and little less for 20 cm depth.



Fig. 8. Correlation between outdoor relative humidity and: a) 2 cm depth measurement values; b) 20 cm depth measurement values.

Rain load events with the total amount of rain 1 mm or greater are shown in Fig. 9. Total rain event is greater between 1st and 2nd measurement, than between the 2nd and 3rd measurements. That could explain the sudden drop of average moisture values in the 3rd measurements (in 19th January). Moreover, the 4th and 5th measurements, that have shown the highest average moisture values, are made right after the rain event.



Rain load Measurement date

Fig. 9. Rain load event during the monitoring period.

24-hour cumulative rain events of three consecutive days prior to the measurements are presented in Fig. 13. When comparing Fig. 7 with Fig. 10, it can be seen that on the 12th February when the total rain load is higher (by 9.5 mm), the average 2 cm depth measurement is slightly lower (by 18.01) than on March 5th. However, the rain load during March 5th is higher (by 4.9 mm) than on February 12. After comparing average moisture values of 2 cm depth measurements with the rain event from Fig. 10, it can be seen that the average moisture value is affected more by the rain load event 24-hours before the measurement, rather than total rain load event of the 3-day period prior to the measurement.



Fig. 10. Rain load of three days prior to the measurement.

The dominant winds and wind speeds during the monitoring period are shown in Fig. 11. Over the period of three days prior to the measurements on 12th February and 5th March, the following wind conditions were observed:

- 12th February 58.46 % of wind comes from the South, followed by 13.58 % from South-West with a dominant speed of 5 m/s;
- 5th March 47.69 % of wind comes from the South west followed by 18.6 % from South, with a dominant speed of 3 to 5 m/s.



Fig. 11. Wind direction and speed during the monitoring period.

Fig. 12 present relative humidity and temperature measurements during the monitoring period. It can be seen that relative humidity under the insulation material stays mainly below 80 % that has been considered as the critical moisture when the mold growth would occur. Relative humidity fluctuates during the monitoring period from 58.85 % to 83.9 % and on the average is 74 %. It also can be seen that temperature under the insulation material stays above 0 °C that reduces the risks of freeze thaw cycles to occur. During the monitoring period temperature fluctuates from 5 °C to 11.5 °C and on the average is 8.4 °C.



Fig. 12. Relative humidity in the insulation system.

4. CONCLUSIONS

The main goal of this research is to study application of internal insulation in historic buildings by assessing the possible moisture sources in the external wall and their impact on moisture content and moisture transport in the wall.

Obtained results show the loss of external plaster is obvious in many areas of the façade, combined with cracks, and cuts. These open areas allow outdoor moisture i.e. wind driven rain, to easily penetrate the wall. Algae growth on the façade indicates that rain water has been present on the walls' surface.

Measurement results also show that moisture content is building up during the autumn and winter periods. This is strongly influenced by outdoor moisture, both relative humidity and rain load events. The dominating wind during the monitoring period was from the same direction as the assessed façade is facing (SE), indicating that wind driven rain could be the reason for the accumulation of moisture in the masonry.

Outdoor weather conditions also have an effect on the interstitial conditions between the layers of the insulation and the external wall. But no interstitial condensation has been observed during the monitoring period. Highest relative humidity beneath the insulation material during the monitoring period reaches 84 % and for most of the time relative humidity stays under 80 %. Such moisture conditions do not cause high risk of mold growth. Results from biological assessment of insulation sample taken from the wall show no signs of mold presence.

No clear signs of rising damp problem were observed during the monitoring period. But as the monitoring period took place only seven months in the cold period of the year, rising damp problem could still be a problem during the spring and warm months of the year.

It must be considered that the non-homogeneity of the façade could be the reason for the fluctuations of the measurements, especially the 2 cm depth measurements close to the surface.

For more conclusive results, monitoring should be continued for at least one full year. Wind driven rain measurements on the façade and continuous moisture monitoring at different heights of the masonry will be performed.

ACKNOWLEDGEMENT

This research is funded by the Ministry of Economics of the Republic of Latvia, project "Improvement of building energy efficiency technologies", project No. VPP-EM-EE-2018/1-0003.

REFERENCES

[1] Policy Pathways Modernising Building Energy Codes. Int. Energy Agency, 2013. [Online]. [Accessed: 01.02.2019] Available:

https://cleanenergysolutions.org/sites/default/files/documents/2013-08-20-modernising-building-energy-codes.pdf

- [2] Albatayneh A., Alterman D., Page A., Moghtaderi B. The significance of building design for the climate. Environmental and Climate Technologies 2018:22:165–178. doi:10.2478/rtuect-2018-0011
- [3] Historical building types and combinations of structural solutions and main driving forces promoting renovation of historic buildings based on case studies. Report. EU project Robust Internal Insulation of Historic Buildings (RiBuild), project No. 637268: 2015.
- [4] De Rosa M., Bianco V., Scarpa F., and Tagliafico L. A. Heating and cooling building energy demand evaluation; a simplified model and a modified degree days approach. *Applied Energy* 2014:128:217–229. doi:10.1016/j.apenergy.2014.04.067
- [5] European Commission. Directive 2010/31/EU Of The European Parliament And Of The Council of 19 May 2010 on the energy performance of buildings (recast). *Official Journal of the European Union* 2010:153.
- [6] Ratnieks J., Jakovics A., Gendelis S. Wall assemblies U-value calculation in test buildings using constant power heating. *Energy Procedia* 2018:147:207–213. doi:10.1016/j.egypro.2018.07.061
- [7] Albatayneh A., Alterman D., Page A., Moghtaderi B. The Significance of Temperature Based Approach Over the Energy Based Approaches in the Buildings Thermal Assessment. *Environmental and Climate Technologies* 2017:19:39–50. doi:10.1515/rtuect-2017-0004

- [8] Franzoni E. Rising damp removal from historical masonries: A still open challenge. Constr. Build. Mater. 2014:54:123–136. doi:10.1016/j.conbuildmat.2013.12.054
- Krawczyk D. A., Wadolowska B. Analysis of indoor air parameters in an education building. *Energy Procedia* 2018:147:96–103. doi:10.1016/j.egypro.2018.07.038
- [10] Jimenez-Bescos C., Prewett R. Monitoring IAQ and thermal comfort in a conservation area low energy retrofit. *Energy Procedia* 2018:147:195–201. doi:10.1016/j.egypro.2018.07.055
- [11] Adhikari R., Lucchi E., Pracchi V. Experimental measurements on thermal transmittance of the opaque vertical walls in the historical buildings. PLEA2012 Conf. Oppor. Limits Needs Towar. an Environ. responsible Archit., 2012.
- [12] Hola A. Measuring of the moisture content in brick walls of historical buildings the overview of methods. IOP Conf. Ser. Mater. Sci. Eng. 2017:251:012067. doi:10.1088/1757-899X/251/1/012067
- [13] Rosina E. When and how reducing moisture content for the conservation of historic building. A problem solving view or monitoring approach? J. Cult. Herit. 2018:31:S82–S88. doi:10.1016/j.culher.2018.03.023
- [14] Barreira E., Almeida R. M. S. F., Delgado J. M. P. Q. Infrared thermography for assessing moisture related phenomena in building components. *Constr. Build. Mater.* 2016:110:251–269. doi:10.1016/j.conbuildmat.2016.02.026
- [15] Jana seta [Online]. [Accessed 15.03.2019]. Available: https://www.kartes.lv/lv/
- [16] Practice handbook for multifunction measuring meter T3000 (EN) [Online]. [Accessed: 01.02.2019] Available: https://uk.trotec.com/fileadmin/downloads/Multifunktion/T3000/TRT-PH-T3000-WM-001-EN.pdf
- [17] LEGMC [Online]. [Accessed: 10.03.2019] Available: https://www.meteo.lv/



Ritvars Freimanis received M. sc. degree in Environmental Engineering by graduation both Riga Technical University and Vilnius Gediminas Technical University in 2019. Since 2017 he works as a scientific assistant at Institute of Environmental and Energy Systems at Riga Technical University, Riga. He is involved in EU research project *RIBuild* that develops guidelines on how to install thermal insulation on historic buildings.



Rasa Vaiskunaite defended dissertation in the field of Technological Sciences (Environmental Engineering Sciences Field, 04T), Vilnius Gediminas Technical University (VGTU), 2004. Master of Natural Sciences (Ecology), Vilnius University (VU), 2000. Bachelor of Natural sciences (Biology), Vilnius Pedagogical University (VPU), 1998. Work experience. Doctoral student (Ph. D.) of Technical Sciences (from 2000) in the Vilnius Gediminas Technical University (VTU): Assistant of the Environment

Gediminas Technical University (VGTU, formerly VTU); Assistant of the Environment Protection Department (from 2002) in VGTU; Associate Professor of the Environment Protection Department (from 2004) in the VGTU; Vice-Dean of the Environmental Engineering Faculty (from 2005) in VGTU; Professor of the Environment Protection and Water Engineering Department (from 2015) in VGTU.

Author prepared more than 73 scientific publications: 1 monograph, 1 handbook, 3 training books, 68 publications, 1 patent. Author participated in 16 conferences (7 of them international – in Sweden, Greece, Russia, Bulgaria etc.), Chairman of the Organizing Conferences "Environmental Engineering"

Committee in 4 International Conferences "Environmental Engineering".



Tereza Bezrucko, Senior expert and project administrative manager at Riga Technical University, Institute of Energy Systems and Environment. Since 2008 Tereza Bezrucko is working at Riga Technical University. The main research area of the Author is analysis and planning of economic processes at local and international levels. She has been involved in more than 40 EU and national research projects.



Andra Blumberga, Dr.sc.ing., professor, works for Institute of Energy Systems and Environments, Riga Technical University since 2001.

She has been working with energy efficiency since 1992. Her main research interest is energy efficiency both from technical and policy sides.

She has managed many national and international research and other projects since 1999, e.g. "Assessment on energy efficiency and use of renewable energy sources in Latvia by 2020", "Climate Technology development modelling in energy sector", "Energy strategy 2030 for Latvia", "System Dynamics modelling for energy sector in Latvia".

She has been working as the World Bank energy expert for development of the Green Investment Scheme in Latvia. She is author of more than 80 publications and 14 monographs. ORCID ID: <u>https://orcid.org/0000-0002-4712-4794</u>